

# METCO METAL FINISHING, INC.

June 11, 2001

Robin Holloway  
Mailcode: WST-3-1  
RCRA Enforcement Section  
U.S. EPA, Region 9  
75 Hawthorne St.  
San Francisco, CA 94105

RE: WST-3-1

Robin,

Metco Metal Finishing is requesting a 30 day extension on the compliance issues.


Status on item #1 is as follows: We are in the process of treating the totes and will have the required aisle space. The system is not at full capacity and the suppliers of the waste treatment equipment are working on start-up and de-bugging and indicated the system will be fully operational this week. Metco will have the storage totes completely treated by next week if there are no further problems with the system and start-up.

Status on item #2 is as follows: The alarm system has been installed (see pictures) and we are planning a plant wide training sessions which includes training on the alarm system next Tuesday and Wednesday.

If you have any questions please call me at the below number.

Thank you,

Mark Williams  
Technical Director




# METCO METAL FINISHING, INC.




Alarm speaker is located  
inside adjacent to the  
chemical storage area.

Alarm speaker



Alarm Button in  
chemical/hazardous waste  
storage area with  
instructions in English and  
Spanish



## METCO METAL FINISHING, INC.

June 11, 2001

Robin Holloway  
Mailcode: WST-3-1  
RCRA Enforcement Section  
U.S. EPA, Region 9  
75 Hawthorne St.  
San Francisco, CA 94105

RE: WST-3-1

Robin,

Metco Metal Finishing is requesting a 30 day extension on the compliance issues.


Status on item #1 is as follows: We are in the process of treating the totes and will have the required aisle space. The system is not at full capacity and the suppliers of the waste treatment equipment are working on start-up and de-bugging and indicated the system will be fully operational this week. Metco will have the storage totes completely treated by next week if there are no further problems with the system and start-up.

Status on item #2 is as follows: The alarm system has been installed (see pictures) and we are planning a plant wide training sessions which includes training on the alarm system next Tuesday and Wednesday.


If you have any questions please call me at the below number.

Thank you,

Mark Williams  
Technical Director




## METCO METAL FINISHING, INC.



Alarm speaker is located  
inside adjacent to the  
chemical storage area.

Alarm speaker



Alarm Button in  
chemical/hazardous waste  
storage area with  
instructions in English and  
Spanish

# METCO METAL FINISHING, INC.

3508 E. Corona Avenue  
Phoenix, AZ 85040  
602-276-4120 FAX 602-276-0109

To: Robert Holloway Date: 6/11/01

Company: \_\_\_\_\_ Fax # \_\_\_\_\_

From: Mark Pages:           

Comments: